

SQASATTESTATION

This is to confirm that an SQAS Tank Cleaning Assessment has been carried out by Belmonte, G. (-) at

SERVI-RUTA LOS MELLIZOS SLU GUARROMAN -JAEN

on May 18, 2016

The assessment covered the
"Core" and "Cleaning Specific" elements
and has been carried out using the
Cefic SQAS Tank Cleaning Questionnaire and Guidelines.

The assessment report has been entered in the Cefic SQAS Electronic Database (www.sqas.org) under reference number 84326 and is accessible to the assessed company, the members of the SQAS Service Group and the Logistics & Distributors User Group.

Issued on May 18, 2016

Victor Trapani SQAS Manager

Cefic, Brussels

Signed

The SQAS assessment report is a statement of facts and this attestation does not express any appreciation of the company's performance. The SQAS Assessment is valid for 3 years.



